General Aviation Joint Safety Committee

GA Aircraft Exhaust Systems

Outreach Guidance & Notes Document

2022/12-07-277(I)PP

This outreach guidance is provided to all FAA and aviation industry groups that are participating in outreach efforts sponsored by the General Aviation Joint Safety Committee (GAJSC). It is important that all outreach on a given topic is coordinated and is free of conflicts. Therefore, all outreach products should be in alignment with the outline and concepts listed below for this topic.

Outreach Month: September 2024

Topic: Exhaust Systems

The FAA and industry will conduct a public education campaign emphasizing the benefits of proper inspection and maintenance of General Aviation Aircraft Exhaust Systems.

Background:

The General Aviation Joint Safety Committee (GAJSC) has studied a number of General Aviation accidents that feature causal factors associated with improper inspection and/or maintenance of General Aviation Exhaust Systems.

Teaching Points:

- Proper inspection and maintenance of aircraft exhaust systems is essential to safety..
- Defective exhaust systems pose significant fire hazards.
- Defective exhaust systems may introduce carbon monoxide into cabin air supplies.
- Replacement of worn or defective exhaust system components is preferrable to repair.
- Pilots should ensure that maintenance personnel workin on exhaust systems be qualified and equipped with proper tools.

References:

<u>Aircraft Exhaust Systems</u> Course ALC-498 on FAASafety.gov

Aircraft Exhaust Systems

Abstract: Lasting 15 to 20 minutes, this presentation discusses proper inspection and maintenance of General Aviation aircraft exhaust systems.

Format: Information Briefing - Power Point presentation

Required Personnel – FAASTeam Program Manager or designated FAASTeam Rep (s)

Optional Personnel – CFIs, Aircraft Mechanics, and inspectors who can speak on GA aircraft exhaust systems.

Natonal FAASTeam Support:

In addition to this guidance document, a Power Point presentation that supports the program is provided. FPMs and presenters are encouraged to customize this presentation to reflect each individual program.

Slides	Script
The National FAA Safety Team Presents Tople of the Month September Echanate System 3 Annual System 3 Neuroscience (NASAdeg Team (NASThern)	Slide 1 2022/12-07-277(I)PP Original Author: Ken Kelley (08/30/2023); POC Guy Minor, AFS-8500 Airworthiness Program Manager, Office (707-704-3530); revised by: Original
	Presentation Note: <i>This is the title slide for Mufflers & Exhaust Systems</i>
	Presentation notes (stage direction and presentation suggestions) will be preceded by a Bold header : the notes themselves will be in Italic fonts.
	Program control instructions will be in bold fonts and look like this: (Click) for building information within a

	slide; or this: (Next Slide) for slide advance.
	Some slides may contain background information that
	supports the concepts presented in the program.
	Background information will always appear last and will
	be preceded by a bold Background: identification.
	We have included a script of suggested dialog with each
	slide. Presenters may read the script or modify it to suit
	their own presentation style.
	The production team hope you and your audience will
	enjoy the show. Break a leg!
	(Next Slide)
Welcome	Slide 2
Emergency Evacuation Bravia Sponsar Acknowledgment Sat phones & suggers to wient or off Other information	Presentation Note: Here's where you can discuss venue
0	logistics, acknowledge sponsors, and deliver other
	information you want your audience to know in the
	beginning.
	You can add slides after this one to fit your situation.
	(Next Slide)
Overview • lyows of extracet systems • Multier and Heat	Slide 3
Escalangeri Hegara vanilkeplacemente Joint types V-Band Pinges valianstes - Accident Cases	The General Aviation Joint Safety Committee has noted
* u van anne une une une une une une une une une	accident causes related to inadequate and inspection of
	aircraft exhaust systems. This program will discuss
	common General Aviation exhaust systems, repair or
	replacement of exhaust system components, and
	methods of joining components. We'll also look at some

	relevant accident cases.
	Presentation Note: If you'll be discussing additional
	items, add them to this list
	(Next Slide)
The Problem	Slide 4
eyaan dalara Usaa ayaa dalaa Usaa ayaa taya	NTSB Date from 2011 through 2019 reveals that there
	have been 23 accidents/incidents directly linked to
	exhaust system failures in various GA aircraft
	incorporating multiple engine types.
	(Next Slide)
History • There have been several V-bandlasheaut system balance that have anyoted	<u>Slide 5</u>
academia. • Lhave have prospiled Anverthiness Directives as well as manufactures's Directives as well as manufactures's Directives as well as manufactures's manufactures and the second s	The pilot of a turbocharged aircraft who experiences a sudden unexplained loss of manifold pressure in-flight
	should assume that an exhaust failure may have occurred and put the airplane on the ground at the earliest
	possible moment. If the aircraft is a twin, the pilot should
	consider shutting down and securing the engine to
	minimize the threat of in-flight fire.
	(Next Slide)
Muffler and Heat Exchangers • Futures in the heat eschanger surface allow exhaust gases to exceed directly into the eaction heat system.	Slide 6
First Escherger area	Air circulating around the engine exhaust pipes warms
	many light airplane cabins. The most common exhaust
	system component failures are muffler or exhaust gas-to-
	air heat exchanger related. Failures in the heat exchanger
	surface (usually in the outer wall) allow exhaust gases to
	escape directly into the cabin heat system. This can result

	in carbon monoxide (CO) exposure. When this occurs in
	a plane, the result could be an accident.
	(Next Slide)
The Problem The PANe concerned about CA whiston system tetrane continuing to contribute to sociolarity incoments Mutter trafficers - terrarity tetras, editerral mosts	Slide 7
Edward syster viska – enviska fitma (CD protorogi Edward syster viska – het in protorogi CO and the system of the	The most common exhaust system failures contributing to General Aviation accidents are Muffler Failures – internal baffles and external mounts. Exhaust system leaks leading to noxious fume/CO poisoning. Exhaust system cracks causing heat impingement/fire.
	(Next Slide)
	Slide 8 WPR19FA178: The pilot and passenger departed from a paved runway on a local flight in an amphibious airplane. The passenger described the airplane's rate of climb after takeoff as "slow" and stated that it was apparent that the plane would not clear the 50-ft-tall trees ahead. A witness described the aircraft as "struggling to gain altitude" and noticed a "definite power loss." The pilot performed a forced landing on a river, where the plane immediately nosed over and began filling with water. The landing gear was extended, and the water rudders were retracted. The landing gear position indicators were operational and indicated that the landing gear was extended. The position of the landing gear likely resulted in the airplane nosing over upon impact with the water. An examination of the engine revealed that the muffler baffles had broken at the weld point. The left muffler baffling moved freely inside the muffler. The right

	muffler baffling was turned 180° and obstructed the
	exhaust outlet. A test run of the engine with the mufflers
	installed was unsuccessful; however, upon removal of
	the mufflers, the engine was performed with no
	anomalies. There is no requirement to check the inside of
	a muffler during annual or 100-hour inspections to
	ensure that the baffling is intact. How long these mufflers
	had been in this condition could not be determined. The
	airflow restriction caused by the separated baffling likely
	resulted in a partial loss of engine power and the
	airplane's subsequent inability to climb after takeoff.
	(Next Slide)
Replace or Repair? Replace - New or record fored components - Owelford more station	Slide 9
· COMPARE INCOME	It is generally recommended that exhaust stacks,
	mufflers, tailpipes, etc., be replaced with new or
	reconditioned components by a qualified repair station
	rather than repaired. Special jigs, tools, and welding
	skills are needed to make a proper repair.
	(Next Slide)
Other Exhaust Components	Slide 10
	Nearly all maintenance and inspections address
	situations with the potential for significant damage or
	harm if not performed correctly.
	Increastors sim to identify deficiencies and confirm the
	inspectors aim to identify deficiencies and commune
	an worthiness status to reduce the likelihood of mishaps.
	Exhaust system components require special attention.
	A primary reason for most exhaust system failures is

	inadequate and infrequent inspections/checks and the
	need for routine and preventive maintenance between
	inspections. Exhaust systems deteriorate due to engine
	operating temperatures, vibrations that cause metal
	fatigue in stress concentration areas, and wear at joints
	or connections.
	(Next Slide)
V-Band Usage	Slide 11
 V-band clemps have become the preferred connection for many exhaust or intake systems. 	Side 11
- 38-	V-band clamps have become the preferred connection
	for many exhaust or intake systems.
	(Next Slide)
Theory of operation • The V-band he applies a uniform and equal closing force around the entire crountenence of the langue.	Slide 12
Once tightands, inclose between the Hanges and V-returner actually reduce the load on the bolt and clamp.	As torque is applied to the coupling nut, the retainer
() <u>()</u>	applies an inward radial force compressing the flange
	together. Unlike bolted flanges, the retainer applies a
	uniform and equal closing force around the entire
	circumference of the flange during and after tightening.
	Once tightened, friction between the flanges and V-
	retainer helps reduce the bolt and clamp load.
	(Next Slide)
V-band Gasket & Safety Wire Comply with the menufacture's metractions for use of V-	Slide 13
	Follow the manufacturers' guidelines in using V-band
Softery WYPe	askets and safety wire to secure the V-band
C Harver -	gaskets and salety whe to secure the v-band.
	(Next Slide)

V-band Cautions - Tubes and components of the coupling must be adapted before installing the coupling. In the fanges must be adapted	Slide 14
 correctly to prevent futures. through the Name and exact before out on the Name before reacting the required larges. 	For a V-band clamp to work correctly, tubes and components of the coupling must be joined and aligned before installing the coupling.
	The flanges must also be aligned correctly before coupling installation to prevent failures.
	Ensure the V-band does not bottom out on the flange before reaching the required torque.
	(Next Slide)
V-band Cautions • The installation process includes proper torque, wating and retorquing the coupling unit the torque value in statute.	Slide 15
 Ispang the coupling with a rubber mails can be even in the coupling while reforming. Selvey one if needed. Misc lynch.ib/sommel Rick 	The installation process should include torquing the latch to its proper torque value, then seating the coupling and re-torquing it until the torque value is stable.
	Tapping the coupling with a rubber mallet can help to seat the coupling while re-torquing.
	Safety wire as needed.
	A link is provided to a YouTube video from GE Aviation which shows a demonstration of installing a V-band. (You must have internet access to make the link work) https://youtu.be/-gimmqTA6zk
	(Next Slide)
Exhaust Failures With extreme frequency of the section of the sec	<u>Slide 16</u>
	Exhaust leaks are inherently much more dangerous than induction leaks, because of the very serious threat of in-flight fire. Fortunately, exhaust leaks are usually a lot
	easier to detect because they typically leave brightly-
	colored exhaust stains (and sometimes obvious heat

damage) that can be detected visually during an enginecompartment inspection.

Next let's take a look at 5 accidents with exhaust system causal factors from the NTSB data base. We've included the NTSB File numbers on screen if you'd like to read the entire reports.

(Next Slide)

Slide 17



CEN17FA207 The private pilot was performing a visual flight rules cross-country flight after purchasing the airplane. After flying for about 1 hr 20 minutes, the aircraft suddenly entered a spiraling descent from cruise flight. Witnesses observed the plane flying erratically at a low altitude before it impacted an open field; they stated that the engine was running until impact. Toxicological testing of specimens taken from the pilot found 55% carbon monoxide saturation in the blood. At carbon monoxide levels above 40%, people typically experience incapacitating symptoms such as severe confusion, agitation, seizures, loss of consciousness, and death. Examination of the airplane's heat exchanger showed that the outside casing had either previously been repaired or had been constructed initially of metals with different properties. About one-half of the casing was discolored and exhibited varying signs of corrosion (the other half did not). Small holes were found where corrosion had occurred in the casing material. The holes from the corrosion provided a means for carbon monoxide to enter the cockpit from the exhaust system.

Federal guidelines for annual aircraft inspections require inspecting the exhaust systems for cracks, defects, and improper attachment during each 100-hour or annual aircraft inspection. Maintenance logbooks indicated that the airplane's most recent annual inspection was completed less than one month before the accident. The available maintenance logbooks did not contain any record of repairs or replacement of the heat exchanger. However, the heat exchanger condition indicates an insufficient annual inspection that did not detect and correct the corroded heat exchanger. (Next Slide) <u>Slide 18</u> CEN17FA207 It is likely that impairment caused by acute carbon monoxide poisoning led to the pilot's loss of airplane control. The corrosion in the heat exchanger allowed carbon monoxide to enter the cabin. Page 2 of 8 CEN17FA207 Probable Cause and Findings The National Transportation Safety Board determines the probable cause(s) of this accident: The pilot's loss of control due to impairment from carbon monoxide poisoning. Contributing to the accident were the corrosion of the heat exchanger and the failure of maintenance personnel to adequately inspect and repair or replace the exchanger during the most recent annual inspection. (Next Slide)



<u>Slide 19</u>

CEN20LA256 The pilot departed in the multi-engine airplane and proceeded east. The aircraft turned north and impacted trees about 30 nm west of the last flight track data. A postimpact fire ensued, and the wreckage was destroyed. A witness driving near the accident site said the airplane flew low, and she thought the aircraft would land. Another witness driving near the accident site, observed the aircraft flying "erratically" with flames emitting from the left engine but did not remember seeing smoke in the sky or from the plane. Another witness near the accident site reported that the aircraft was "sputtering" and "popping" as it flew over his home. Post-accident examination showed that the plane descended through trees and was highly fragmented and mostly consumed by fire. Both propellers had indications consistent with low amounts of rotational energy. The right engine propeller blades were at a blade angle near feather pitch at impact, and the left engine propeller blades appeared fully feathered. All engine control levers were found full forward except the left engine propeller lever, which was full aft.

(Next Slide)



<u>Slide 20</u>

CEN20LA256 Additional examination revealed that the right magneto installed on the left engine would not rotate due to a failed bearing. The failure signatures were indicative of a loss of lubrication in the bearing. The airplane likely experienced at least a partial loss of engine power in the left engine as a result. The evidence is consistent with the pilot attempting to shut down the left engine due to the failed magneto and failing to maintain single-engine flight resulting in an impact with trees and terrain. Both engine exhaust systems were unairworthy due to very thin metal, holes, cracks, and signs of oxidative degradation. Exhaust leaks can result in an inflight fire. However, the post-impact fire prevented determination if an inflight fire occurred, and the witness testimony of flames coming from the engine could not be verified. (Next Slide) <u>Slide 21</u> ERA18LA214 On August 12, 2018, at about 0840 Eastern daylight time, Pipistral Sinus 912, N467L, was destroyed when it was involved in an accident near West Palm Beach, Florida. The private pilot was not injured. The airplane was operated as a Title 14 Code of Federal Regulations Part 91 personal flight. According to the pilot of the motor glider, after dropping off a passenger from a previous flight, he restarted the engine and taxied out to runway 27R. After checking his instrument gauges, he made a radio call indicating that he would remain in the traffic pattern. During takeoff, he noticed the engine sounded "a little rough," as he turned downwind, he started to smell smoke. He shut down the engine and returned for landing. The landing was uneventful, but the pilot noticed flames below the right door when the aircraft stopped. After he exited the

	airplane, the fire grew and eventually consumed the
	airplane.
	(Next Slide)
	Slide 22
<image/>	ERA18LA214 Post-accident examination of the airplane's engine by a Federal Aviation Administration inspector revealed that the fire consumed the cockpit. The motor glider's engine examination revealed that the exhaust manifold was cracked. Further examination of the exhaust manifold by the NTSB Materials Laboratory showed that the fracture and cracking of the exhaust manifold tubes were due to fatigue. In each failed manifold tube, the fatigue cracking initiated on the inner surface near circumferential welds and propagated through to the outer surface, indicating that the fatigue cracks were likely present before the accident. The fatigue cracking at the fitting led to a complete fracture, whereas the cracking in the opposite tube elbow had
	progressed only part way.
	(Next Slide)
	Slide 23
reneration of the second se	ANC16FA065 The private pilot departed in his float- equipped, experimental, amateur-built airplane during day-visual meteorological conditions. According to a friend of the pilot, the purpose of the flight was to fly over a proposed hunting site and then return. About 90 minutes later, multiple witnesses saw the airplane
	complete two low-level, high-speed, 360° right turns over

	a residential neighborhood. The witnesses said the
	airplane's first 360° turn was accomplished at 150 and
	200 ft above ground level, but the second turn was much
	lower. Witnesses near the accident site reported that, as
	the airplane completed the second, steep, 360° turn, the
	nose of the aircraft pitched down, and the plane began a
	rapid nose-down descent. The engine rpm then
	increased significantly, and the wings rolled level just
	before the airplane impacted a stand of tall trees
	adjacent to a home. The aircraft subsequently descended
	onto a neighborhood road and came to rest inverted. A
	post-crash fire ensued about 30 seconds after impact,
	quickly engulfing the entire plane. According to family
	members and close friends, this was highly unusual
	behavior for this pilot.
	(Next Slide)
	(Next Slide) <u>Slide 24</u>
	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's
	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly
e constanti de la constanti de La constanti de la constanti de	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the
view of the second	(Next Slide) Slide 24 ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed
view of the second	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology
variable for the second s	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon
FOR Particular Sector Sect	(Next Slide) Slide 24 ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon monoxide) in the pilot's blood. The pilot was a
x and a set of the	(Next Slide) Slide 24 ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon monoxide) in the pilot's blood. The pilot was a nonsmoker, and nonsmokers normally have no more
variation of the second secon	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon monoxide) in the pilot's blood. The pilot was a nonsmoker, and nonsmokers normally have no more than 3% carboxyhemoglobin. The pilot's cause of death
to the second seco	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon monoxide) in the pilot's blood. The pilot was a nonsmoker, and nonsmokers normally have no more than 3% carboxyhemoglobin. The pilot's cause of death was extensive blunt force trauma, including lacerations
terreturne in the second secon	(Next Slide) <u>Slide 24</u> ANC16FA065 Post-accident examination of the airplane's exhaust system revealed that the muffler can assembly was cracked around most of its circumference near the inlet portion of the muffler, which would have allowed exhaust gases to enter the cockpit/cabin. Toxicology tests revealed 48% carboxyhemoglobin (carbon monoxide) in the pilot's blood. The pilot was a nonsmoker, and nonsmokers normally have no more than 3% carboxyhemoglobin. The pilot's cause of death was extensive blunt force trauma, including lacerations of the aorta, heart, and liver, and there was no soot

	fire, given the extensive blunt force injuries the pilot
	sustained and the lack of soot in his trachea, the pilot's
	elevated carboxyhemoglobin level was likely from acute
	exposure to carbon monoxide during the 90-minute flight
	and not from postimpact fire.
	(Next Slide)
	<u>Slide 25</u>
	WPR15IA263 On September 21, 2015, at about 0645
WARKER Budarqu	mountain daylight time, a Cessna T206H, N7269T,
	experienced an in-flight fire during its initial climb from
	Idaho Falls Regional Airport, Idaho Falls, Idaho. The
	airplane was being operated as an aerial survey flight
	under the provisions of 14 Code of Federal Regulations
	Part 91. The flight instructor and passenger/camera
	operator sustained minor injuries related to smoke
	inhalation. The airplane sustained minor damage. The
	local flight departed Idaho Falls at about 0640; visual
	meteorological conditions prevailed, and no flight plan
	had been filed. The pilot reported that he performed a
	preflight inspection, and the passenger checked the
	external camera equipment before the flight. No
	anomalies were noted, and the engine run-up was
	normal. During the initial climb, the pilot retracted the
	flaps and having reached about 200 ft above ground
	level, the passenger began to see smoke. The pilot
	initiated a turn to the crosswind leg, and smoke rapidly
	filled the cabin. The passenger opened the side window
	and, concerned that it may fan the source of the smoke,
	the pilot asked him to close it. The pilot then put on his

oxygen cannula, but it did not provide relief, and by now he was having trouble breathing due to the smoke density. The smoke was now obscuring the instrument panel, but he could partially see the runway and immediately turned the airplane towards it. He opened his side window and put his head outside for a better view. However, the force of the wind made breathing difficult. The pilot then pushed the airplane's nose down, initiating a steep dive to the runway. He could not recall the final stages of the landing, but as soon as the airplane touched the ground, he applied full brake action, locking up the wheels. Once they had stopped, the pilot shut off the fuel mixture control, and they rapidly egressed.

(Next Slide)



<u>Slide 26</u>

WPR15IA263 The airplane sustained thermal damage to the right side of the firewall, the upper and lower engine cowlings, and the forward right section of the fuselage skin, which had burned through to the cabin at the air inlet door. The fire location being so near the air inlet forced smoke into the airplane's fresh air intake system. Subsequent examination revealed that the wastegate overboard exhaust tailpipe had come away from the turbocharger housing. The turbocharger housing outlet was directly in line with the battery mounting tray on the right side of the firewall. The battery had partially melted, and both its positive and negative electrical connecting cables had partially melted. Both cables exhibited globular damage to their copper conductors

	consistent with arcing and an electrical short circuit.
	Cessna Service Bulletin SB99-71-06, released December
	6, 1999, recommended the installation of a tailpipe
	lanyard to "provide a safety link ensuring positive
	turbocharger exhaust tailpipe retention should the clamp
	become loose." No lanyard was found on the airplane,
	and no record in the maintenance logbooks indicated
	that the service bulletin had been complied with. The
	service bulletin affected 111 Cessna T206H airplanes, and
	records provided by Cessna revealed that in the 2-year
	period Page 4 of 6 WPR15IA263 following issuance of the
	service bulletin, 91 of the service bulletin's sub-assembly
	components were sold, with sales then averaging about 3
	per year through to 2015. Federal Aviation
	Administration regulations do not require compliance
	with service bulletins for aircraft operating under the
	provisions of 14 Code of Federal Regulations Part 91. The
	airplane experienced a similar separation of the tailpipe
	during takeoff on April 28, 2015. On this occasion, smoke
	was again drawn into the cockpit, but damage was
	limited to the battery and its associated cables.
	Maintenance records indicated that the tailpipe clamp
	and gaskets were replaced following the event.
	(Next Slide)
Conclusion • Knowledge as key to the maintenance of estimust systems • Mave appropriate veryous information. • work to low in	Slide 27
 Dang series On each praget When in doubt, get a second opimion. Harmenber: Danger of the and/or carbon monoxide if not maintened. 	A few closing points: Knowledge and education are key
	to the maintenance of exhaust system. Make sure you
	have the appropriated service information. Inspect
	closely. When in doubt, get a second opinion, the

	owner/pilot is relying on you. Remember: there is an increased danger of fire and/or carbon monoxide if the exhaust system is not inspected and maintained in an airworthy condition.
	(Next Slide)
For More Information The ALC-426 Course - Ancraft Ethnust Systemic at AAStantygov: • ancraft adhaud systemic, fyse, repairs,	Slide 28
In all registration and interaction. Image: All and all all all all all all all all all al	The ALC-498 course at FAASafety.gov is designed to give you an overview of guidance about aircraft exhaust systems, types, repairs, and inspections, as well as best practices for maintenance. As Maintenance Technicians, Pilots, and aircraft owners, we encourage you to take this course.
	The QR code on screen will take you to the course. Or
	navigate to faasafety.gov and search the course catalog.
	(Next Slide)
Safety Management Systems (SMS) Coming to General Aviation	<u>Slide 29</u>
Vgs. brow has as detailed an agrand braken at maximum	Safety Management Systems are a set of policies and processes that can increase the safety and efficiency of any flight operation. And FAA is bringing SMS to General Aviation. You may have heard of SMS but thought it was only for large organizations but actually SMS can be scaled to fit any operation large or small.
	There are 4 major components to a Safety Management System (Click)
	Safety Policy – a documented commitment to safety that runs from the head of an organization to its newest member. (Click)

	Safety Risk Management – a process that identifies hazards within an operation, determines to what extent an identified hazard may impact flight safety, and controls the risk of occurrence to an acceptable level. (Click)				
	Safety Assurance – By collecting and analyzing information derived from safety performance data Safety Assurance ensures the performance and effectiveness of Safety Risk Controls. (Click)				
	Safety Promotion communicates safety information and commitment throughout the organization. (Click)				
	You can find more information about Safety Management Systems at the URL on the Screen.				
	(Next Slide)				
Questions?	Slide 30Presentation Note:You may wish to provide your contact information and main FSDO phone number here.Modify with your information or leave blank.(Next Slide)				
Proficiency and Peace of Mind • Prosellerly with goar CPI • PerhesiPraches • Boewards IN WES • December 19 WES • December 20 Perfect • PerhesiPraches • December 20 Perfect • PerhesiPraches • December 20 Perfect • PerhesiPraches • Perhe	Slide 31 There's nothing like the feeling you get when you know you're playing your A game and in order to do that you need a good coach (Click)				
	So fly regularly with a CFI who will challenge you to review what you know, explore new horizons, and to				

	program but it's well worth it for the peace of mind that				
	comes with confidence. (Click)				
	Vince Lombardi, the famous football coach said, "Practice				
	does not make perfect. Only perfect practice makes				
	perfect." For pilots that means				
	flying with precision. On course, on altitude, on speed all				
	the time. (Click)				
	And be sure to document your achievement in the				
	WINGS Proficiency Program. It's a great way to stay on				
	top of your game and keep you flight review current.				
	(Next Slide)				
Thank you for attending • You are what members of our GA safety community.	<u>Slide 32</u>				
	Your presence here shows that you are vital to General				
	Aviation Safety Community members. The high				
	standards you keep and the examples you set are a great				
	credit to you and GA.				
	Thank you for attending.				
The National FAA Safety Team Presents Topic of the Month Sentember	<u>Slide 19</u>				
GA Atronati Systems					
Produced by: The Motions (FM Safety Taxes (FM STaxes)					
	(The End)				

Appendix I – Equipment and Staging

Equipment:

• Projection Screen & Video Projector suitable for the expected audience

- Remote computer/projector control available at the lectern or presenter location
 - In lieu of remote detail a Rep to the computer/projector control.
- Presentation Computer
 - **Note:** It is strongly suggested that the entire program reside on this computer.
- Back up Projector/Computer/Media as available.
- PA system suitable for the expected audience
 - Microphones for Moderator and Panel
 - Optional Microphone (s) for the audience
- Lectern (optional)

Staging:

- Arrange the projection screen for maximum visibility from the audience.
- Equip with PA microphones
- Place Lectern to one side of screen. This will be used by presenters and moderator

•

• **IMPORTANT** – Once you have completed outreach on this topic, please help us track the outreach you have done by entering a SAS record.

NPP14: GAJSC Safety Outreach Topic of the Month

SAS Activity Code	National Use	Primary Area	Keyword	Description	Performance Target	Date Due	LDR 12XXFAFAAST	
1983	NPP14	К	032	Promote "Topic of the Month" within the FSDO area.	1 per FSDO, per Month, per FY	09/15/24	OR0010	
RESOUR	CES:			COMMENTS:				
 Topics of the Month materials are available at the National FAASTeam KSN site under <u>Approved Resources</u>. Each resource supports 10 to 20 minutes of program time. 					 GAJSC Topic of the Month: Industry and the FAASTeam will nationally promote each monthly topic. Use the "teaching points" on the Presenter Notes & Outreach Guidance Document to promote the topic locally in any way possible. 			
NOTES:								
 1 SAS entry at the conclusion of each GAJSC Topic of the Month outreach. 								
 Record the type of outreach conducted in the comment section of the SAS 								
 Points of contact for this NPP item: 								
 John Steuernagle - National FAASTeam Products Manager, (301) 471-3954, John W. Steuernagle@faa.gov 								

Kevin Clover - National FAASTeam Ops Program Manager, (562) 888-2020, <u>Kevin L.Clover@faa.gov</u>