



U.S. Department of Transportation

Federal Aviation Administration

# Airworthiness Concern Sheet

Date: July 8, 2020

<p><b>Reply to:</b>  Name: Boyce Jones  Title: ASE - Propulsion  Office: Atlanta ACO  Department: FAA  Street Address: 1701 Columbia Ave  City, State, ZIP: Atlanta, GA, 30337  Telephone: (404)474-5535  Email: Boyce.Jones@faa.gov</p>	<p><b>Make:</b> Continental Aerospace Technologies, Inc.  <b>Model / Series:</b> O-470-K, -L, -M, -R, -S &amp; -U converted to O-470-50 via STC SE4985NM  <b>Serial Numbers:</b> All Serial Numbers</p> <p><b>Reason for Airworthiness Concern:</b> Continental Aerospace Technologies, Inc. was made aware of an engine that lost power, while in flight, with the pilot smelling smoke in the cockpit, resulting in the pilot conducting a forced landing with no injuries. The investigation found that the modified Continental O-470 engine's crankshaft was fractured between the #5 and #6 cylinders. The engine was originally an O-470 that underwent a conversion via STC SE4985NM, to increase the engine displacement, and STC SE10233SC, to install a supercharger. The crankshaft, which was ground down for reuse and inspected in October 2018, was an Airmelt model (pre-Vacuum Arc Remelt (VAR)) that was not designed to be used on the bigger bore engines (due to the greater strains encountered on those engines, as addressed by Continental CSB96-8 and MSB96-10B). The FAA is concerned that the Airmelt crankshafts are being improperly used in these converted O-470 engine models (renamed O-470-50 as specified in STC SE4985NM), and we would like to gather data to better understand the overall impact on the flying public.</p>
--	---

**Federal Aviation Administration (FAA) Description of Airworthiness Concern**

**Request for Information**

The FAA is requesting the following information from owners and operators of the Continental Aerospace Technologies, Inc. engine models O-470-K, -L, -M, -R, -S & -U that have been converted into an O-470-50 engine model using STC SE4985NM:

- 1) Have you installed STC SE4985NM to convert your O-470-K, -L, -M, -R, -S & -U engine into an O-470-50 by increasing the engine displacement?
- 2) If the answer to question one was 'Yes', have you also installed STC SE10233SC to install a Belt-Driven Vortech V-1S supercharger assembly on the same Continental engine (either before or after STC SE4985NM was installed)? Or any other engine-related STC's in addition to STC SE4985NM?
- 3) If you have an engine with either STC SE4985NM, SE10233SC or both installed, please confirm whether your crankshaft was manufactured using the Airmelt process or the Vacuum Arc Remelt (VAR) forging process (please refer to CSB96-8 for guidance on how to identify your type of crankshaft). If you do not know which process was used for your crankshaft and are unable to determine it, please respond to this question with 'Unknown'.

This Airworthiness Concern Sheet (ACS) is intended as a means for FAA Aviation Safety Engineers to coordinate airworthiness concerns with aircraft owners/operators through associations and type clubs. At this time, the FAA has not made a determination on what type of corrective action (if any) should be taken. The resolution of this airworthiness concern could involve Airworthiness Directive (AD) action or a Special Airworthiness Information Bulletin (SAIB), or the FAA could determine that no action is needed at this time. The FAA's final determination will depend in part on the information received in response to this ACS.

The FAA endorses dissemination of this technical information to all manufacturers and requests association and type club

comments.

<b>Attachments:</b> <input type="checkbox"/> Service Difficulty Report <input type="checkbox"/> Accident/Incident Data System <input checked="" type="checkbox"/> Service Letter / Bulletin <input type="checkbox"/> Special Airworthiness Information Bulletin <input type="checkbox"/> Federal Aviation Administration or National Transportation Safety Board Safety Recommendation <input type="checkbox"/> Airworthiness Directive <input type="checkbox"/> Alternate Means of Compliance <input type="checkbox"/> Risk Analysis <input checked="" type="checkbox"/> Other: ACS Response Sheet	<b>Transmittal:</b> <input checked="" type="checkbox"/> Federal Aviation Administration (FSDO) <input checked="" type="checkbox"/> Airplane Owners and Pilots Association <input checked="" type="checkbox"/> Experimental Aircraft Association <input checked="" type="checkbox"/> Type Club <input type="checkbox"/> Type Certificate Holder <input type="checkbox"/> Other:	<b>Response Requested By:</b> <input type="checkbox"/> Emergency (10 days) <input checked="" type="checkbox"/> Alert (30 days) <input type="checkbox"/> Information (90 days)
--	--	--



- 3) If you have an engine with either STC SE4985NM, SE10233SC or both installed, please confirm whether your crankshaft was manufactured using the Airmelt process or the Vacuum Arc Remelt (VAR) forging process (please refer to CSB96-8 for guidance on how to identify your type of crankshaft). If you do not know which process was used for your crankshaft and are unable to determine it, please respond to this question with 'Unknown'.