

Cessna 182G, Cracked Main Landing Gear Attach Casting, ATA 5343

A general aviation submission states, "A casting crack was visually found during the course of an Annual Inspection. The crack is located on the forward end of the support casting (P/N 07416031), (starting) 0.25 inches from the outboard mount holes and ends within 0.25 inches of the mount holes on the inboard side of the casting."



Part Total Time 2,690 Hours