


Hamilton Standard, 14SF7, Bearing Failure, ATA 6111

(A corporate operator provides the following brief description referencing a de Havilland DHC8 airplane.)


The submitter states, "During inspection/maintenance of the propeller, the L/H number three blade (P/N SFA13M1R0A+D) was found to have bearing failure."



Hamilton Standard, 14SF7, Bearing Failure, ATA 6111



Hamilton Standard, 14SF7, Bearing Failure, ATA 6111



(Time since overhaul: 10,415.0 hours.)

Part Total Time: 46,829.0 hours