

Cessna 172P, Cracked Seat Frame, ATA 2510

A general aviation submitter writes, "The pilot's lower seat frame support legs cracked at the frame rail cut outs (where they attach to the seat height adjustment arms)." (*Seat frame P/N: 05142047.*)



Part Total Time 5,150 Hours