

Cessna 208B, Frayed Flap Cable ATA 2750

A mechanic stated, "During a routine inspection, *(I)* found a flap cable *(P/N 2660001105)* frayed at the connection to the fairlead—about 30 percent of the *(strands)* were broken. *(It)* runs from the inner bell crank to the outer end of the flap. This cable was original as far as can be traced back—the original P/N tag was still installed. *(And)* judging from the slip mark, the cable had not *(moved from its swaged fitting)*."



Total Part Time: (Unknown)