## Cessna: 525C Failed Brake Rotors (friction pad) ATA 3242

A submission from a corporate operator states, "The brake pads on both the L/H and R/H brake rotors are debonding—with 'chunks' missing." (*Rotor P/N: 90006028; Brake Assembly P/N: 90006022. Red arrows are my insertions—Ed.*)





Part Total Time: 302.0 Hours