

Cessna: 550; Cracked Seat Belt Assembly

The upper Seat Base Assembly (*P/N 5519015—15*) was found cracked at the chair back attach points, states this repair station mechanic. "Stress on the chair back and metal fatigue are the probable cause. Also observed was a previous, inappropriate repair.

"This chair was repaired in accordance with STC ST01042WI." (*Seat base P/N: 5519009-21.*)



Cessna: 550; Cracked Seat Belt Assembly



Cessna: 550; Cracked Seat Belt Assembly

(This -21 P/N reflects thirteen times in the SDRS database.)

Part Total Time: (unknown)