


## Cessna 560XL, Broken ECU Aspirator Tube, ATA 3600



An unidentified submitter provides this defect report. *"(I) discovered this ECU aspirator high pressure tube...broken on preflight. I also found the bias bleed air tube chafed. This condition appears to be (caused) by poor tube routing, (creating) ongoing chafing over an unknown amount of time." (No part numbers were provided with this report. But a couple of nice photos leave little doubt as to which tube is in reference. The photos are distorted vertically—Ed.)*



**Cessna 560XL, Broken ECU Aspirator Tube, ATA 3600**



**Cessna 560XL, Broken ECU Aspirator Tube, ATA 3600**



Part Total Time: 1,378.0 hour