



### **Gulfstream 690B, Cracked Main Gear Strut, ATA 3213**

"The left main gear strut was flat," writes a technician. "(We) tried to service (*the strut*), but when we applied nitrogen pressure, hydraulic fluid came out of a three-inch crack in the strut body and bearing assembly...." (P/N: ES12394.)



**Gulfstream 690B, Cracked Main Gear Strut, ATA 3213**



Part Total Time: 6,842.0 Hours