

Bell: 206L.1; Improper Governor Assembly; ATA 7323

The governor allows the engine (Allison 250C28) to over-speed," says a mechanic. It failed the shop test. Engine was disassembled and found it improperly assembled. The spool bushing anti-rotation tang was engaged in the lever slot." (There are 16 SDRS database entries for the Honeywell Governor P/N: 252469211, and 6 entries for the Bushing Assembly P/N: 2526146





