

## **Continental GTSIO520L, Broken Camshaft Gear, ATA 8520**

### **Continental: GTSIO520L; Broken Camshaft Gear; ATA 8520**

"(I) was complying with AD 07-05-15 and performing an Annual Inspection," states this submitter, "when I found one broken tooth on the camshaft gear. No other indications were found of related defects or damage, internally or externally, after the engine was disassembled. And no metal (or the gear tooth) was found in the oil filter or internal to the engine. (Note:) The camshaft gear P/N 656914 supersedes P/N 537432."



**Continental GTSIO520L, Broken Camshaft Gear, ATA 8520**



Part Total Time: 1,828.0 hours