

## Continental IO550N Cracked Exhaust Manifold (2), ATA 7810

(This is the second of two reports describing defects on the exhaust systems of this Cirrus SR22 aircraft.)

More thoroughly described in the previous report, the same submitter provides this second report and photos. "During routine maintenance, (we) found the L/H exhaust manifold had cracked into two pieces between cylinder numbers two and four." (Exhaust P/N: 226850002.)



**Continental IO550N Cracked Exhaust Manifold (2), ATA 7810**



Part Total Time: 990.0 Hours