

Kelly Alternator ALU8521, Broken Brush-block Wire, ATA 2421

Kelly Alternator: ALU8521; Broken Brush-block Wire; ATA 2421

(This report references a Diamond DA40 aircraft sporting a Lycoming IO360 engine.)

A repair station technician states, "This alternator failed in flight. (I) found the brush-block wire broken."

