

Beechcraft E90, Cracked Wing Spar Caps

An unknown submitter says, "The forward outboard, lower wing spar caps are cracked. *(These cracks—on both L and R assemblies...) radiate out from the fourth Huck rivet forward, (passing) through the wing attach hinge.*

"This aircraft was inspected 15 months ago (404.2 hours) by eddy current. No cracks were found at that time."

(Wing lower spar cap part numbers: L/H: 000-110012-1; R/H: 000-110012-2).

Part Total Time: 8,875.6 hours.

Beechcraft E90, Cracked Wing Spar Caps