



Cessna CE-750, Water Separator Corrosion, ATA 2170

A repair station mechanic states, "Both the L/H and R/H water separators have corrosion under the insulation (P/N 5715526-8). This is an area not normally looked at during the water sock cleaning/restoration." (Reference *United Technologies, Hamilton Standard; model EC22DWS-1; P/N 79030103.*)



Cessna CE-750, Water Separator Corrosion, ATA 2170



Part Total Time: Unknown

November 2012 AC 43-16A

Cessna CE-750, Water Separator Corrosion, ATA 2170