

CASA C212CC, Cracked Horizontal Stabilizer Attach Fittings, ATA 5551

The aircraft, which was previously reported for a different defect, has another defect. The submitter states, "Three each horizontal stabilizer attach fittings (fuselage side) were found to be cracked, and three others were found with inter-granular corrosion. Six of the eight (fittings) are beyond limits (P/N 2122415XX)."



CASA C212CC, Cracked Horizontal Stabilizer Attach Fittings, ATA 5551



CASA C212CC, Cracked Horizontal Stabilizer Attach Fittings, ATA 5551

Part Total Time: 16,761.0 Hours