


# **Cessna 172S, Frayed Aileron Cable, ATA 2710**

"During a routine inspection," says a flight school submitter," the Aileron Cable (P/N 0510105-364) was found shiny (worn) where it passes through the ceiling pulley cluster. When the mechanic viewed through a strong magnifying glass, he could see many broken strands.



**Cessna 172S, Frayed Aileron Cable, ATA 2710**



**Cessna 172S, Frayed Aileron Cable, ATA 2710**



Part Total Time: 2,311.0 Hours