

Cessna 425, Avionics Master Switch, ATA 2460

This defect report states, "The avionics master switch (P/N CM358950) was found inoperative upon a functional check. The part has been red-tagged and replaced with a new switch. The *(failed switch)* was disassembled, and upon further inspection it appears to have a manufacturer's defect." *(The manufacturer's name is Potter. This P/N is reflected ninety times in the SDRS database! Note the similarities in the failed switch description in the second Beechcraft article to the following photo.)*



Part Total Time: 4,679.0 hours

Cessna 425, Avionics Master Switch, ATA 2460