

## Champion 7ECA, Cracked Wing Spar, ATA 5711

A repair station technician writes, "A required inspection of wooden wing spars in accordance with AD 2000-25-02 revealed a compression crack in the left wing forward spar at the top, O/B of the wing-strut attach doubler-plate." (*The part number listed is 5-271L.*)



Part Total Time: (2,573.1 hours).