



Photo 1 – Elevated view of the damaged empennage (courtesy of the operator).



Photo 2 – Elevated view of the right side engine and fractured upper cowling (courtesy of the operator).



Photo 3 – Ground view of the damaged empennage (courtesy of the Federal Aviation Administration).



Photo 4 – Ground view of the damaged empennage (courtesy of the Federal Aviation Administration).



Photo 5 – View of the exemplar upper and lower left side engine cowlings (courtesy of the Federal Aviation Administration).




Photo 6 – View of the fractured upper and missing lower right side engine cowlings (courtesy of the Federal Aviation Administration).