

EAA Chapter 203 Monthly VMC Club Meeting

The EAA VMC Club provides a "hangar flying" experience organized around visual flight, in order to promote safety, education, and proficiency. Every meeting consists of a scenario presentation and group discussion about unusual or interesting charts, changed rules and procedures, and member experiences. We also have occasional guest speakers.

The scenario(s) we will discuss at this meeting is/are: "Upside Down."

You a Private Pilot with ~65 hours flight time in PA-28-180 Cherokee, preparing for a one-hour afternoon flight in a rented Piper PA-28-180 Cherokee equipped for both VFR & IFR flight. Some areas of marginal weather are reported along the route.

Bring your EFB, your experience, and your questions, and be ready to participate.

Event Details

Sat, Feb 14, 2026 at 10:30 EST

F45 North County General Aviation Airport

11250 Aviation Blvd
Hanger 5

West Palm Beach, FL



Contact: Eric G. Flraig

5613290985

egflraig@gmail.com

Select #: SO19141423

**Representative MILDRED ANITA
MIXON n/a**

All are welcome. You do not need to be an EAA member to attend

We will also be discussing how you can earn **WINGS** Credit.

Florida Turnpike to Exit 107 Bee Line Highway. Head West on Bee Line Highway towards North Palm Beach Country General Airport. Turn left onto Aviation Road. Follow Aviation Road to Hangar 5 on the left.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.