



**Heavily worn threads caused by use of an unapproved compound in a threaded rod end installation.**