

Crack origination at spot-weld.