FEDERAL AVIATION ADMINISTRATION

FLIGHT ADVISORY
GPS INTERFERENCE TESTING

FCAR 17-07 (FORT CARSON)

3-4 March, 2017
Fort Carson, CO

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal:

A. Location: Centered at 383140N1045445W or the PUB VOR 293 degree radial at 27NM.

B. Dates and times:
3 – 4 MAR 17 2000Z – 2300Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV (FCAR GPS 17-07) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 51NM RADIUS CENTERED AT 383140N1045445W (PUB 293027) FL400-UNL CHANGING IN AREA WITH ALT DEFINED AS:
51NM RADIUS AT FL250
48NM RADIUS AT 10000FT
48NM RADIUS AT 4000FT AGL
69NM RADIUS AT 50FT AGL

E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

Released
28 February, 2017



FCAR 17-07
GPS INTERFERENCE TESTING