## Cessna 404, Damaged Elevator Mount Brackets ATA na

"While this aircraft was tied down," says a submitter, "the control wheel was secured in the full up position with a seat belt—instead of the approved gust lock device. This (ad hoc arrangement) allowed the elevators to have some movement—high winds prior to the intended flight (allowed the elevator) to hammer its lower stop until the bracket's upper mounts failed.

"The pilot stated he conducted a flight control check prior to taxi—everything felt fine. It was not until the control surface (incurred) an air load that he discovered a problem and aborted the takeoff."



Cessna 404, Damaged Elevator Mount Brackets ATA na



## Cessna 404, Damaged Elevator Mount Brackets ATA na



(No P/N's were provided with this report. Red arrows are my insertions—Ed.)

Total Part Time: (Unknown)