


Hawker 800XP, Cracked MLG Door Bracket, ATA 5280

A general aviation submitter writes, "During base maintenance, (we) found the R/H main landing gear door support cracked (P/N 25FC5804)."



Hawker 800XP, Cracked MLG Door Bracket, ATA 5280



Hawker 800XP, Cracked MLG Door Bracket, ATA 5280

