

Goodrich, Water Heater. Failed Thermostat

(The following description references a Bombardier BD1001A10.)

"The 'Lavatory Water' circuit breaker popped," says this writer. "(We) found the water heater to be at fault. We removed the plastic cover on the heater and found the thermostat body had separated (from a poor solder joint) which exposed the contacts and shorted-out the unit. The heater was manufactured in May of 2008." (Goodrich Water Heater P/N: 4E31762. Klixon Thermostat P/N: 4391S1471.)



Part Total Time: 563 Hours