


Boeing 747-409, Arcing Lamp Holders, ATA 3320

A foreign repair station submitter writes, "The cabin log records the first class galley, number one work light as 'inoperative'. (We) removed this light and found the light assembly lamp holders had arced. The galley ceiling was checked (for water leakage)—none was found. This light assembly was replaced."



(MSN 29906) GALLEY 1 WORK LIGHT ASSY HOLDERS
ARCED

Part Total Time: (unknown)