


## Boeing 747, Burned Light Controls, ATA 3300

A field submitter advised that a foreign airline sent a control panel (P/N 69B46111-10) to our repair station. This panel was badly burned; we believe either it was the cause of a fire or it burned when an adjacent panel caught fire.

We contacted the airline to find out if this incident was reported and to determine if other panels had been sent to our repair station that may have been similarly exposed. They have not responded at this time.



Boeing 747, Burned Light Controls, ATA 3300



## Boeing 747, Burned Light Controls, ATA 3300



Part Total Time: Unknown

Boeing 747, Burned Light Controls, ATA 3300