

Cessna 208B, Leaking Brake Castings, ATA 3242

An unidentified submitter wrote that the main casting housing the brake caliper pistons leaks fluid under normal braking pressures. These leaks are from excessive porosity in the casting.

This is the second occurrence we have experienced in our operation; the first was not reported.” (Brake Caliper Housing P/N 160-11800. Caliper Assembly is by Cleveland; P/N 163030-1001)

Part Total Time: 194.6