

AirVenture 2025 Seaplane Base Forum - Seaplanes and Weather

Seaplanes used to have unique weather challenges, but as more new entrant aircraft are flying in urban environments and areas lacking collocated certified weather sensors, many of the weather challenges faced by seaplane pilots are similar to weather challenges facing Advanced Air Mobility (AAM and Unmanned Aircraft Systems (UAS). This forum will discuss several weather-related hazards and ongoing research to resolve them. Challenges to be discussed include adverse winds, conflicting weather observations, lack of a collocated certified weather sensor, and cognitive errors along with techniques being researched by the FAA to reduce or resolve these challenges for seaplanes, AAM, and UAS flights.

WINGS credit available!

To receive WINGS credit fill out attendance sheet available at the Forum entrance.

Event Details

Wed, Jul 23, 2025 at 13:30 CDT

**FAA Safety Forum/EAA
AirVenture Seaplane Base**

5202 Streich Lane

Oshkosh, WI



Contact: Jay M Flowers

(000) 000-0000

jay.m.flowers@faa.gov

Select #: AFS0136942

Administrator Jay Flowers n/a

The daily FAA Safety Forum at the EAA AirVenture Seaplane Base is located under the large tent at 96WI or (N43°56.47' W88°29.62'). If you drive, the address is 5202 Streich Lane, Oshkosh, WI 54902. Phone number to the Base is 920-230-7829 (AirVenture week only).

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.