

## Loss of Control: A Review of the JFK, Jr. Accident (Click link inside for a video trailer of event)

Video Trailer In 1999, John F. Kennedy, Jr. got in the left seat of his new plane with his wife and her sister for a trip to a wedding. They never made it. We'll unravel the causes and factors of this "loss of control" accident while learning of other loss of control factors we can avoid.

**Directions:** Take Hwy 412 westbound past the airport to the south bypass. The restaurant has a large sign!

### A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at [www.FAASafety.gov](http://www.FAASafety.gov)!

### Event Details

Thu, Sep 12, 2013 - 6:30 pm

**Grecian Steak House**

1108 South Bypass

Kennett, MO 63857



Contact: Phil Dixon

(314) 890-4818

[phil.dixon@faa.gov](mailto:phil.dixon@faa.gov)

Select #: CE0351738

FPM PHILIP WADE DIXON

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.