MN FAASTeam presents:

Observations From Instrument Practical Tests

This presentation will look at instrument practical tests from an examiner's point of view. As an instrument pilot the risks and safety analyses are elevated over a VFR rating. As instrument pilot applicant, safety of flight should always be of the highest priority. Helpful hints for the instrument practical test for the instructor and student will be offered.

Tony Hentges has been flying for over 30 years. Once he had all his ratings, he began flight instructing, later moving on to flying Part 135, corporate, and now flying for a Part 121 carrier. Tony has been an examiner for the past 13 years primarily doing single engine practical tests. He really enjoys flying general aviation and tries to focus on risk management/safety and basic stick and rudder skills.

Seminar in Hangar A

Airport is located southeast of the City of Buffalo off of Highway 55. Turn north on County Road 134 (at the Kwik Trip) and the airport will be on your right just past Menards. It is easy to find using GPS/map apps.

Event Details

Fri, May 16, 2025 at 10:30 CDT Buffalo Municipal Airport 1305 County Road 134 Buffalo, MN



Contact: Ashlyn Landa (612) 367-7708 director@mnpilots.org Select #: GL15137036 Representative Mark Cook n/a Self serve fuel available with credit card.

Signs will be provided to guide you to parking.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to https://www.wingsindustry.com/WINGS-Sweepstakes for more info. Join us on Facebook: https://www.facebook.com/groups/GASafety/

Join us on Facebook: https://www.facebook.com/groups/GASafety/ Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.