

Training on Garmin Repair Station Manual Revision on ACP-0015

1 hour of Repair Station Document recurrent training on ACP-0015.

ACP-0015 is used to identify and control the capabilities list of articles the Garmin AT Aircraft Repair Station (CRS 9GTR079B) hereinafter referred to as repair station, can approve for return to service. All articles that the Garmin AT Aircraft Repair Station is approved to work on will be included in this list.

Directions: Garmin Facility Birddog Conference Room

A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at www.FAASafety.gov!

Event Details

Wed, Dec 10, 2014 - 09:00 PST

Garmin AT

2345 Turner Road SE

Salem, OR 97302



Contact: DEAN ALLEN BOEDIGHEIMER

(503) 391-3236

dean.boedigheimer@garmin.com

Select #: NM0958549

Representative DEAN ALLEN

BOEDIGHEIMER

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.