

September Topic of the Month - GA Aircraft Exhaust Systems

Concerned about carbon monoxide in the cockpit or a fire caused by exhaust system failure? The General Aviation Joint Safety Committee has noted accident causes related to inadequate care and inspection of aircraft exhaust systems. This program will discuss common General Aviation exhaust systems, repair or replacement of exhaust system components, and methods of joining components. What should you look for as Pilot in Command? We'll also look at some relevant accident cases.

From CAE, head south on Airport Blvd. Take the right onto Air Commerce Dr. and then right onto SC-602. Turn left onto Ermine Rd. In 1.5 miles, turn left onto US-1 S/Augusta Rd. Follow US-1 S into Lexington. At the intersection of Rt 378, continue straight ahead onto Old Chapin Rd and then make a left turn into the Flight Deck parking lot in 500 ft. The Flight Deck Restaurant is in the center of the shopping complex. The entrance is easily found off the courtyard near Barnes Jewelers and Horizon Travel.

Event Details

Mon, Sep 23, 2024 at 18:30 EDT

Flight Deck Restaurant

109 Old Chapin Rd

Lexington, SC



Contact: JAY SEWARD

(803) 361-1463

sewardje2@yahoo.com

Select #: SO13132342

**Representative JAY EMRIE
SEWARD n/a**

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

**Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faa.gov!**

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.