

CFIT Hazards include Towers Visual Traps and Rapid Weather Changes

Controlled Flight Into Terrain (CFIT) doesn't require mountains — Central Florida pilots contend with tall towers, cranes, antennas, and dense obstacle clusters under the KORL Class B shelf, plus deceptive night-over-water horizons, wetland featureless-terrain illusions, and sudden visibility drops from fast-moving summer convection or haze. This seminar examines local CFIT precursors, from automation slip-ups in congested airspace to database gaps on obstacle locations, and delivers strategies to spot and counter these risks early.

Please download and review the documents below at "Additional Event Documents" and please visit the Orlando Executive Airport FAASTeam Library web site:

<https://www.fsr-inc.org/FAAST/Seminar/Notice.aspx>

Event Details

Thu, Nov 13, 2025 at 19:00 EDT
Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL



Contact: Robert Breaux
407-644-4298

FAASTeam@CenturyLink.net

Select #: SO15138661

**Lead Representative Robert
Breaux n/a**

From Colonial Drive turn south on Rickenbacker Dr. continue through the Fairgreen St intersection to the end of Rickenbacker Dr. and into the parking lot. Park in any available designated spot. Walk east to the Airport Administration Building.

Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL 32802

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faa.gov!

The FAA Safety Team (FAASteam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.