

FAA ACO Rotorcraft Directorate presents:

2018 International Rotorcraft Safety Conference

This safety conference will provide the latest information and updates for all aspects involving Rotorcraft covering operations, maintenance, safety systems, equipment, personnel and training. Industry and FAA experts will cover a myriad of subjects ranging from current and proposed regulatory activates, industry initiatives, accident case studies and mitigating strategies. EASA will present its top International issues.

Event Details

Tue, Oct 23, 2018 - 09:00 CDT
Hurst Conference Center / Hurst
Texas

1601 Campus Drive
Hurst, TX 76054



Contact: Eugene Trainor
((817) 222-5123
eugene.trainor@faa.gov

Select #: SW1985874
FPM Darrell Hughes

Directions: DRIVING FROM DALLAS

From TX-183/TX-121 West

- Exit Precinct Line Road
- Continue through the light
- Turn right on Campus Drive

DRIVING FROM FORT WORTH

From TX-183/TX-121 East

- Exit Precinct Line Road
- Turn left on Precinct Line Road
- Turn left on Thousand Oaks Drive

DRIVING FROM DFW INTERNATIONAL

South Entrance

- Take TX-183 West for approximately 8 miles
- Exit Precinct Line Road
- Continue through the light
- Turn right on Campus Drive

DRIVING FROM DFW INTERNATIONAL

North Entrance

- Take TX-114/TX-121 South for approximately 3 miles
- Merge onto TX-121 South towards Fort Worth for approximately 10 miles
- Exit Precinct Line Road
- Continue through the light
- Turn right on Campus Drive

A message from the National FAASafety Team Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASafety Team) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.