

Inflight Engine Failure - How an Engine Monitor Kept Me from Pulling the Chute

A seemingly routine flight from TOA to SEZ in a Cirrus SR22 required quick decisions when the oil pressure started dropping rapidly. After safely on the ground at KRAL, a failure analysis was performed looking for the cause. Diagnostics led to an engine overhaul which is fully explained, and sample parts from the engine are shown .

Directions: Northwest of VNY airport on Balboa between Roscoe and Stagg Street.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to www.wingsindustry.net for more info.

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Sign up for the FAA's safety services at www.FAASafety.gov!

Event Details

Sat, Apr 8, 2023 - 09:00 PDT
Clipper Aviation at Terminal
Building Prop Park
7900 Balboa Room 108
Van Nuys, CA 91406



Contact: Richard Mend
(818) 636-1021

mendaviation@sbcglobal.net

Select #: WP05121056
Representative RHON WILLIAMS

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.