## FAASTeam presents:

## IFR Flying to Monterey (Available in-person and online)

Monterey Airport (KMRY) is a well-known destination for Bay Area pilots. However, like many seaside airports, KMRY is frequently covered in marine layers. During winter, low visibility and low ceilings can make flying VFR quite challenging. The safest way to reach KMRY is to fly IFR.

This seminar, Part 2 of 3 IFR Flying Series, is designed to provide a comprehensive understanding of what to expect on an IFR flight. You will learn:

- Why flying IFR makes you a safer and more proficient pilot

- How to plan an IFR flight from Reid Hillview San Jose (KRHV) to Monterey (KMRY) and back

- How to communicate with ATC during an IFR departure, en-route, and arrival

## Event Details

Sat, Dec 9, 2023 at 13:00 PST

Aerodynamic Aviation

2650 Robert Fowler Way

San Jose, CA



Contact: Thao Do 5712490421 thaodofly@gmail.com Select #: WP15125488 Representative Thao Do n/a - How to manage your crew resources with your copilots and passengers

- How human factors and spatial disorientation can influence your flight

Whether you're interested in learning IFR or are already an IFR-rated pilot seeking proficiency and currency, this seminar is for you. Once you've experienced flying IFR, you'll wonder how you ever flew without it!

Enter through the main lobby door and turn left into the classroom.

## A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to https://www.wingsindustry.com/WINGS-Sweepstakes for more info. Join us on Facebook: https://www.facebook.com/groups/GASafety/

Join us on Facebook: https://www.facebook.com/groups/GASafety/ Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.