



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY
GPS Testing
ACC GPS 11-72
October 7, 2011 – October 8, 2011, & October 17, 2011
Pinon Canyon, CO

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 373000N/1035621W or the TBE VOR 311.9 degree radial at 21.7NM.

B. Dates and times:

07-08 OCT 1900-2200Z
17 OCT 0200-0400Z

C. Duration: Each event may last up to 3 hours and may start at any time during the requested periods.

D. During testing, the GPS signal may be unreliable or unavailable within a 340NMR centered at 373000N/1035621W or the TBE VOR 311.9 degree radial at 21.7 NM at FL400 and above, decreasing in area with decrease in altitude to 290NMR at FL250, 180NMR at 10,000 FT MSL, 200NMR at 4,000 FT AGL and 155NMR at 50 FT AGL.

E. Pilots are strongly encouraged to report anomalies during testing to the appropriate ARTCC to assist in the determination of the extent of GPS degradation during tests.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

**ACC 11-72
GPS INTERFERENCE TESTING**

