

FEDERAL AVIATION ADMINISTRATION  
HOUSTON INTERCONTINENTAL TOWER  
4215 WILL CLAYTON PARKWAY  
HOUSTON, TEXAS 77032

ISSUED: January 1, 2014

EFFECTIVE: January 1, 2014

HOUSTON GEORGE BUSH INTERCONTINENTAL TOWER LETTER TO AIRMEN  
NO. 14-01.

SUBJECT: MOVEMENT AREAS ON HOUSTON GEORGE BUSH INTERCONTINENTAL  
AIRPORT THAT ARE NOT VISIBLE FROM THE AIRPORT TRAFFIC CONTROL  
TOWER.

CANCELLATION: January 1, 2016.

1. BACKGROUND. Some portions of movement area are not visible from the control tower at Houston George Bush Intercontinental Airport and are described in Section 2. This letter serves to notify all pilots that ATC services in these areas are limited as described in Section 3.

2. NONVISIBLE MOVEMENT. Use caution, the following areas are not visible from the Houston (IAH) Tower cab:

- a. Portions of Taxiways WA and WB from WH to the approach end of Runway 33R.
- b. Taxiways WA and WB from WE to WW.
- c. Taxiway WD from WA to NR.
- d. Taxiway NR from NC to WB.
- e. Taxiway WL from Runway 15L to WB.
- f. Taxiway WM.
- g. Dual entry Taxiways WV and WW at the approach end of Runway 15L.

3. ATC SERVICES PROVIDED. Houston (IAH) ATC Tower will provide air traffic services in the above area based on known traffic.



Donald B. Baker  
Air Traffic Manager  
Houston Intercontinental Tower