

FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING FCAR 15-07 18 December 2015 Fort Carson, CO

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal:

- A. Location: Centered at 383140N 1045437W or the PUB VOR 293 degree radial at 27NM.
- B. Dates and times: 18 Dec 15 1500Z 2159Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV (FCAR GPS 15-07) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVAILABLE WITHIN A 41NM RADIUS CENTERED AT 383140N1045437W (PUB 293027) FL400-UNL DECREASING IN AREA WITH A DECREASE IN ALTITUDE DEFINED AS:

41NM RADIUS AT FL250, 41NM RADIUS AT 10000FT, 41NM RADIUS AT 4000FT AGL, 38NM RADIUS AT 50FT AGL

E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

