

FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING

BLISS 18-01 (FORT BLISS)

25 February – 5 March 2018 Fort Bliss, TX

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 321608N 1060603W or the ELP VORTAC 011-degree radial at 029NM.
- B. Dates and times: 25 FEB 5 MAR 18 0300Z 1500Z 1830Z 2230Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV GPS (BLISS GPS 18-01) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 158NM RADIUS CENTERED AT 321608N1060603W (ELP011029) FL400-UNL, 153NM RADIUS AT FL250
 126NM RADIUS AT FL250
 126NM RADIUS AT 10000FT
 123NM RADIUS AT 4000FT AGL 90NM RADIUS AT 50FT AGL.
- E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

