

FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING

BLISS 18-02 (FORT BLISS)

19 - 23 February 2018 Fort Bliss, TX

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 323120N1053953W or the ELP VORTAC 028-degree radial at 52NM.
- B. Dates and times: 19 23 FEB 18 1700Z 2200Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV GPS (BLISS GPS 18-02) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 15NM RADIUS CENTERED AT 323120N1053953W (ELP028052) FL400-UNL, 16NM RADIUS AT FL250 16NM RADIUS AT 10000FT 16NM RADIUS AT 4000FT AGL 22NM RADIUS AT 50FT AGL.
- E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

