


# SC00

Triple Tree Aerodrome



# DEPARTURE ADVISORY

REFERENCE ONLY



## ***DEPARTING 03***

- Turn to heading 360 before the departure end of the runway (if safely able) and fly 3 NM, then proceed on course.

## ***DEPARTING 21***

- Maintain runway heading until reaching 3 NM or 2,000 MSL, then proceed on course.