



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING

FORT CARSON COLORADO (FTCRCO) 23-60


**05 – 06 October
Fort Carson, CO**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Centered at 383042N1045356W or the PUB VOR 293 degree radial at 26 NM.
- B. Dates and times (**Dates and times are based on GMT (Z).**):

05 – 06 OCT 23 DLY 0531Z – 1159Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV GPS (FTCRCO GPS 23-60) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 234NM RADIUS CENTERED AT 383042N1045356W (PUB293026) FL400-UNL, 203NM RADIUS AT FL250, 143NM RADIUS AT 10000FT, 128NM RADIUS AT 4000FT AGL, 92NM RADIUS AT 50FT AGL.
- E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FTCRCO GPS 23-60 GPS INTERFERENCE TESTING