



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING

FORT RILEY KANSAS (FTRLKS) 25-59

**06 – 15 September
Fort Riley, KS**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Centered at 391236N0965000W or the SLN VOR 058-degree radial at 40 NM.

B. Dates and times (**Dates and times are based on GMT (Z).**):

06 – 08 SEP 25 DLY 0600Z – 0959Z


14 – 15 SEP 25 DLY 0600Z – 0829Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (FTRLKS GPS 25-59) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 29NM RADIUS CENTERED AT 391236N0965000W (SLN058040) FL400-UNL, 30NM RADIUS AT FL250, 30NM RADIUS AT 10000FT, 30NM RADIUS AT 4000FT AGL, 16NM RADIUS AT 50FT AGL.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FTRLKS GPS 25-59 GPS INTERFERENCE TESTING