

HOTSPOT 2 AWARENESS


Pilots are reminded to exercise increased vigilance in the vicinity of **Hotspot 2 (TWY D / TWY K near RWY 35 and RWY 27R)**.

Recent pilot deviations have involved aircraft continuing on Taxiway D instead of turning onto Taxiway K as instructed.

To reduce the risk of a runway incursion:

- Review the airport diagram prior to taxi.
- Confirm taxiway identification before crossing any runway.
- Closely monitor hold short instructions.
- If uncertain of your position or clearance, stop and contact ATC.

PHL ATCT may provide additional directional instructions to assist pilots operating in this area.



When approaching Hotspot number 2 from the north Taxiway D has additional markings on the pavement to indicate the turn onto Taxiway K

The hold short bar for Runway 17/35 is canted towards Taxiway D for visibility.

