

AirVenture 2025 Forum - ODPs and SIDs

Whether I am doing an FAA Instrument Checkride, CFI-Instrument Airplane, 61.58, 135.293, 135.297, or a 121.141 proficiency check, I see pilots struggle with Standard Instrument Departures (SIDs) and Obstacle Departure Procedures (ODPs). The standard instrument departure is based on a minimum climb gradient of 200 feet per nautical mile (NM). However, when a SID or an ODP shows a minimum climb gradient of say, 310 feet per NM, I ask the student if that is higher or lower than the standard climb gradient. I have been dismayed that nearly half of the responses are wrong. So, I thought we should take a closer look at this topic. This subject gets even more confusing when we discuss One Engine Inoperative (OEI) or engine out procedures.

WINGS credit available!

To receive WINGS credit fill out attendance sheet available at the Forum entrance.

Event Details

Sat, Jul 26, 2025 at 10:15 CDT

**FAA Safety Center/EAA
AirVenture**

3110 Knapp Street

Oshkosh, WI



**Contact: Jay M Flowers
(000) 000-0000**

jay.m.flowers@faa.gov

Select #: AFS0136936

Administrator Jay Flowers n/a

The FAA Safety Center is centrally located on the EAA AirVenture grounds on the South side of the control tower. We are the large tan building with the rooftop deck facing the runway. Forums entrance is on the west side of the building.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.